

Port-to-Port (s charts)

- Mean SD for port-to-port by metric, level, machine

	Monitor				Merit				Next			
	58	59	60	61	58	59	60	61	58	59	60	61
CO	.47	.53	.47	.45	.42	.48	.46	.38	.16	.16	.15	.13
PUFF	.14	.16	.15	.13	.21	.20	.18	.18	.15	.20	.16	.15
TPM	.78	.84	.73	.76	.46	.42	.41	.37	.16	.19	.17	.18
NIC	.03	.02	.03	.03	.03	.03	.03	.02	.01	.01	.01	.01
H2O	.34	.38	.39	.37	.10	.10	.08	.07	.03	.05	.04	.04
TAR	.51	.49	.37	.43	.38	.37	.34	.32	.15	.19	.16	.18